


FIG. 1








Fig. 3





IF USERS ARE EXPERIENCING FAST BUSIES WHILE TRYING TO MAKE A CALL FROM A CELL SITE THEN IT CAN BE DUE TO

- *ANTENNAS IN THE CELL ARE DOWN
- *CELL SITE IS DOWN COMPLETELY
- *SEVERAL RADIOS IN THE CELL ARE NOT WORKING
- *POWER SUPPLY TO THE CELL SITE IS DOWN END IF

Fig. 5



CELL 76 HAS 1 FACE CELL 76 HAS 3 RADIOS

ETC.

ETC.

ETC.

Fig. 6

1 'K + A




Fig. 7